


PIPER

23-250T AIR RESEARCH



AD 68-21-03 on tailpipes, if cracked or deformed replace.

Check Plenum's flow divider plates for cracking and warping

Check Plenum's for heat distortion

ITEM	OEM PART NO	DESCRIPTION	Condition
01	286-P23-024-119	LE INBD STK	OH
02	286-P23-024-115	LE OTBD STK	OH
03	286-P23-060-3	LH PLENUM	OH
04	286-P23-060-5	LH TAILPIPE	OH
05	286-P23-024-121	RE INBD STK	OH
06	286-P23-024-117	RE OTBD STK	OH
07	286-P23-060-7	RH PLENUM	OH
08	286-P23-060-9	RH TAIL PIPE	OH
09	116933-225-3	BYPASS FLANGE	OH
NS	17189-225	SEAL	NEW
NS	24502-225	CLAMP	NEW
NS	77611	GASKET	NEW