


**BEECHCRAFT**

**35 TC (Continental System)**



**AD 89-24-03** on header part #642668 if cracks are found replace with part # 646795  
 Inspect header for cracks  
 Inspect heater core heat fins for cracking and distortion

ITEM	OEM PART NO	DESCRIPTION	Condition
01	642670	CYL #1 RR	OH
02	642671	CYL #2 LR	OH
03	642672	CYL #3 RC	OH
04	642671	CYL #4 LC	OH
05	642673	CYL #5 RF	OH
06	642674	CYL #6 LF	OH
07	642666	RH ELBOW	OH
08	642663	HEATER ASSEMBLY	OH
09	642891	LH SLEEVE	OH
10	646795	HEADER	OH
10	654340	HEADER	OH
11	642392	TAILPIPE	OH
11	655164	TAILPIPE	OH
12	642665	BYPASS ELBOW	OH
NS	628260	GASKET	NEW