


AERO COMMANDER

680 B



Inspect tailpipes for cracking and heat distortion

Tailpipe has center flow divider. Inspect tailpipes for cracking and heat distortion

Entire slipjoint assembly should be ordered or send in entire system for fixturing purposes.

ITEM	OEM PART NO	DESCRIPTION	Condition
01	5610333-503	RH STACK	OH
01	636-6	RH STACK	OH
02	5610333-501	LH STACK	OH
02	636-3	LH STACK	OH
03	621-83	RH FWD STACK	OH
04	621-70	LH FWD STACK	OH
05	621-81	RH CTR STACK	OH
06	621-71	LH CTR STACK	OH
07	621-90	RH AFT STACK	OH
08	621-72	LH AFT STACK	OH
NS	15486	GASKET	NEW