


CESSNA

411



Subject to AD 2000-01-16

AWI is authorized by the FAA to meet the overhaul requirements (paragraph "G") on AD 2000-01-16.

- Visual inspection every 50 hrs. or 30 days
- Remove tailpipes inspect for cracks every 12 mo.
- Inspect & pressure test exhaust system every 12 mo.
- Replace multi-segment V-band clamps every 500 hrs.
- Remove the exhaust system from the slip joints aft to all turbo charger components every 2,500 hrs. or 12 yrs. which ever occurs first.

- Check all Slip Joints for Freedom of movement
- Check all parts for internal pitting

ITEM	OEM PART NO	DESCRIPTION	Condition
01	8109-102	EXHAUST STACK ASSY	OH
02	995-54	ELBOW	OH
03	995-50	CROSSOVER	OH
04	995-3	EXHAUST STACK ASSY	OH
05	9910314-1	SLIP JOINT	OH
05	994-20	SLIP JOINT	OH
06	994-61	LH TURBO INLET	OH
07	995-62	LH BY-PASS ELBOW	OH
08	995-58	LH TAIL PIPE	OH
09	8108-101	EXHAUST STACK ASSY	OH
10	996-46	CROSSOVER	OH
11	996-52	ELBOW	OH
12	996-4	EXHAUST STACK ASSY	OH
13	996-54	RH TURBO INLET	OH
14	996-55	RH BY-PASS ELBOW	OH
15	996-58	RH TAIL PIPE	OH
NS	1001-6	SPRING KIT	NEW