


PIPER**34-200 SENECA I**

AD 83-14-05 Inside baffle of tailpipe must be inspected every 100 hrs with a boroscope after the accumulation of 1050 hrs.

ITEM	OEM PART NO	DESCRIPTION	Condition
01	78463-06	LH OTBD COLLECTOR	OH
02	78463-07	LH OTBD RISER	OH
03	78463-04	LH INBD COLLECTOR	OH
04	78463-02	LH INBD RISER	OH
05	78463-10	LH TAIL PIPE	OH
06	78463-09	LH TAILPIPE SHROUD	OH
07	78463-05	LH SHROUD	OH
08	78463-13	RH INBD COLLECTOR	OH
09	78463-12	RH INBD RISER	OH
10	78463-15	RH OTBD COLLECTOR	OH
11	78463-16	RH OTBD RISER	OH
12	78463-18	RH TAILPIPE	OH
13	78463-14	RH SHROUD	OH
14	78463-17	RH TAILPIPE SHROUD	OH
15	CLAMP	RISER CLAMP 1.75	NEW
16	78463-08	TAILPIPE CLAMP	NEW
NS	487-696	TAILPIPE HANGER	OH
NS	78463-11	TAILPIPE HANGER	OH
NS	970	GASKET	NEW