


BEECHCRAFT**58 BARON**

Check diameter of exhaust system should be either 2" or 2.5" more commonly 2"

Inspect all slip joints for freedom of movement and leakage

Inspect tailpipes for pitting and wall thickness

ITEM	OEM PART NO	DESCRIPTION	Condition
01	58-950000LO-R	LE OTBD 4 PIECE STACK ASSEMBLY	OH
01	58-950000RI-R	RE INBD 4 PIECE STACK ASSEMBLY	OH
02	58-950000LI-R	LE INBD 4 PIECE STACK ASSEMBLY	OH
02	58-950000RO-R	RE OTBD 4 PIECE STACK ASSEMBLY	OH
03	58-950002-9	LH FWD RISER	OH
04	58-950002-33	RH FWD RISER	OH
05	58-950000-5	LH CENTER RISER	OH
06	58-950000-7	RH CENTER RISER	OH
07	58-950000-11	RE INBD TAILPIPE	OH
07	58-950000-9	LE OTBD TAILPIPE	OH
08	58-950000-13	LE INBD TAILPIPE W/EGT	OH
08	58-950000-15	RE OTBD TAILPIPE W/EGT	OH
09	96-950002-47	STUB RISER	OH
10	96-950000-33	TAIL PIPE 1/2 CLAMP	NEW
NS	628260	GASKET	NEW