


**MOONEY**

**M-20 200 SLIP RIB M20J**



Check for baffles, cracked or heat distortions on the muffler body. Shroud must be removed for complete muffler body inspection.

Muffler outershell are hydroformed to reduce stress

ITEM	OEM PART NO	DESCRIPTION	Condition
01	630045-503	200 SLIP RIB MUFFLER	OH
02	630053-511	RF RISER	OH
03	630053-507	RR RISER	OH
04	630053-509	LF RISER	OH
05	630053-513	LR RISER ASSY	OH
06	630053-013	LR RISER UPPER	OH
07	630053-015	LR RISER LOWER	OH
08	630119-501	TAILPIPE	NEW
09	630057-000	SHROUD	OH
10	C10Y-30-6C	CLAMP	NEW
11	C10X-30C	CLAMP	NEW
NS	630053-TSK	TAILPIPE SPRING KIT	NEW
NS	77611	GASKET	NEW