


**CESSNA  
P210R & T210R**



Pay special attention to the following areas:

- A. Cracking and heat distortion
- A. Inspect center plate
- B. Heat distortion

Check all slip joints for freedom of movement and metal galling.

ITEM	OEM PART NO	DESCRIPTION	Condition
01	2154025-1	RH COLLECTOR	OH
02	2154025L	LH STACK ASSY	OH
03	2154002-5	RISER	OH
04	2154025-10	CROSSOVER	OH
05	2154023-1	LF RISER	OH
06	2154027-7	LC RISER	OH
07	2154026-1	LR RISER	OH
08	1250860-117	RISER	OH
09	2154029-10	TAILPIPE	OH
10	2154000-66	TUBE ASSY	OH
NS	628260	GASKET	NEW