


GRUMMAN


AA5 TRAVELER SN# 0001 TO 640



Muffler must have baffles intact to be airworthy.

ITEM	OEM PART NO	DESCRIPTION	Condition
01	099001-148	MUFFLER	OH
02	099001-120	STRAIGHT RISER	OH
03	RISER CLAMP	1 3/4" RISER CLAMP HALF	NEW
NS	099001-140	SHROUD	OH
NS	77611	GASKET	NEW

AA5 TRAVELER SN # 0640 AND UP



2 LH risers have a slight curve
2 RH risers are straight

Muffler must have baffles intact to be airworthy.

ITEM	OEM PART NO	DESCRIPTION	Condition
01	099005-195	MUFFLER	OH
02	099005-102	RISER	OH
03	099005-194	CURVED RISER	OH
03	RISER CLAMP	1 3/4" RISER CLAMP HALF	NEW
NS	099005-197	SHROUD	OH
NS	77611	GASKET	NEW