


CESSNA

303 CRUSADER



AD 85-23-06 inspect turbo inlet for exhaust gas leakage

Check all parts for internal pitting

A Check overlays on inside for cracking

B Check tailpipes for pitting and ball socket wear

ITEM	OEM PART NO	DESCRIPTION	Condition
01	2554029-1	LH TAILPIPE	OH
02	2554021-1	LE TURBO INLET	OH
03	2554017-2	LE INBD AFT RISER #1	OH
03	2554017-25	LE INBD AFT RISER #1	OH
04	2554017-24	LE INBD CTR RISER #3	OH
04	2554017-4	LE INBD CTR RISER #3	OH
05	2554017-23	LE INBD FWD RISER #5	OH
05	2554017-6	LE INBD FWD RISER #5	OH
06	2554017-30	LR COLLECTOR TUBE	OH
07	2554017-27	LE OBT AFT RISER #2	OH
08	2554023-1	RE OBT CTR RISER #4	OH
09	2554017-9	RE OBT FWD RISER #6	OH
10	2554029-2	RH TAIL PIPE	OH
11	2554021-1	RE TURBO INLET	OH
12	2554018-32	RE COLLECTOR TUBE	OH
13	2554018-28	RE OBT AFT RISER #1	OH
14	2554023-1	RE OBT CTR RISER #3	OH
14	2554023-3	RISER CLY #3	OH
15	2554020-2	CYL # 3	OH
16	2554017-21	RISER CLY # 5	OH
16	2554017-9	RISER CLY # 5	OH
17	2554018-10	LH FWD RISER	OH
18	2554018-24	RE OBT FWD RISER #6	OH
18	2554018-8	RE OBT FWD RISER #6	OH
19	2554018-6	RE OBT CTR RISER #4	OH
20	2554018-2	RE OBT AFT RISER #2	OH
20	2554018-26	RE OBT AFT RISER #2	OH