


**PIPER****23-250 C-F AZTEC**

**AD 72-14-05** 100 hr. repetitive inspection of entire exhaust system. Adjust and align per Service Bulletin 319

ITEM	OEM PART NO	DESCRIPTION	Condition
01	28279-02	RE FRONT OTBD	OH
02	28279-03	RE REAR OTBD	OH
03	28279-14	RH CROSSOVER	NEW
04	33420-02	RH INBD STACK	OH
05	28278-02	LE FRONT OTBD	OH
06	28278-03	LE REAR OTBD	OH
07	28278-12	LH CROSSOVER	NEW
08	33419-03	LH INBD STACK	OH
09	33538-00	BRACKET ASSEMBLY	OH
09	33540-00	HANGER	OH
NS	14235-02	EXHAUST STACK SUPPORT CLAMP	NEW
NS	14235-13	SHROUD TAKEOFF CLAMP	NEW
NS	14235-18	SHROUD TAKEOFF CLAMP	NEW
NS	32217-00	SHROUD TAKE OFF ASSY	OH
NS	32275-00	SHROUD CLAMP	NEW
NS	32275-03	SHROUD CLAMP	NEW
NS	33178-02	SHROUD TOP	OH
NS	33178-03	SHROUD BOTTOM	OH
NS	33178-04	SHROUD TOP	OH
NS	33178-05	SHROUD BOTTOM	OH
NS	33419-02	LH OTBD STACK	OH
NS	33420-03	RH OTBD STACK	OH
NS	40123-100	SHROUD SAFETY CABLE	NEW
NS	77611	GASKET	NEW